

PERRY TWP  
T8N  
2594.13'

SECTION 2  
RIW  
2594.13'

101.64' SKEW  
126.06' SKEW

26.40' SKEW

2362.8'

21

N 01° 02' 06" W

PERRY  
CITY

2464.44'

2640.0'

2640.0'

10

12

11

13

14

2643.96'

2643.96'

PERRY TWP  
T8N  
2597.76'

SECTION 3  
RIW  
2597.76'

95  
COULD FIND NO  
RECORD OF OWNERSHIP

147

2277.0'

2362.8'

PERRY  
CITY

2640.0'

2640.0'

2628.78'

2628.78'

# Section 1

1. Bd of Commissioners of Mon. Co

124 9-21-59

not recorded?	
------------------	--

Sr. of Metro  
Politan  
Sch. Bd.

INTERSECT N. BOUNDARY 261 LINKS  
(172.26 ft.) E. OF POST SECS.

32 & 33 T-9-N, R-1-W.

SECTION

4


TOWNSHIP

8-N

RANGE

1-W

INTERSECT N. BOUNDARY 437 LINKS  
(288.42 ft.) E. OF POST SECS.  
33 & 34 T-9-N, R-1-W.



11  
2362.80  
2640.00  
5002.80

1  
2277  
2640.  
4917

4982.80  
4917.00  
85.80

PERRY TWP  
T8N  
2698.08'

SECTION 4  
RIW  
2698.08'

2362.80'

2277.0'

PERRY  
CITY

1  
COULD  
FIND NO  
RECORD OF  
OWNERSHIP

2640.0'


2640.0'

2626.14'


2626.14'







SECTION 6  
RIW





T8N  
-1320.0'

RIW  
-1320.0'



PERRY TWP  
T8N

SECTION 7  
RIW  
2640.00

61.38  
SKEW

2752.20

43.56  
SKEW

NE OF NW  
ALL NEEDS  
RESURVEYED  
NONE OF IT  
MATCHES UP  
INCORRECT STARTING  
PTS, INCORRECT  
DIMENSIONS

2713.26

2640.00'

2713.26


2640.00'


127.36  
SKEW


2770.02'

2640.00'

D TAYLOR







PLAT 13 CLAIMS 1.96A BY DEED BUT 2.08 IN TRANSFER BOOK

PLATS 96, 100-102, 105 ARE NOT STARTED AT CORRECT PNT ACCORDING TO DEED DIST FROM START TO ROAD INCORRECT

PLATS 10, 15, 19 DO NOT HAVE DISCRPTIONS, ASIDE FROM LEGAL

PLATS 106, 107, 109 ALL DISC START AT WRONG CORNER SHOULD BE NW CORNER OF NE, SE

PLAT 108 TOO MUCH ACREGE SHOULD BE 222 ACCORDING TO BOOKS, 242 IS DISCRIBED

D TAYLOR

PERRY TWP  
T8N  
2628.78'

SECTION 10  
RIW  
2628.78'

42.90'  
SKEW

36.30'  
SKEW

PLATS  
112, 113  
48, 11, 61  
ALL TAKEN  
INCORRECTLY  
LOCATED PLAT

2640.0'


PLAT 11  
OVERLAPS  
PLAT 48

PLAT 35, 43  
IN CORRECT  
STARTING  
PIN

PLATS 107, 108  
ALL DISC  
INCORRECT  
STARTING PNT  
USING GIVEN  
STARTING PNT  
ALL WOULD BE  
IN SEC 9


2640.0'


PLAT 127  
INCORRECT  
STARTING PNT  
PLAT 125  
INCORRECT  
ACREAGE



2632.08'  
D. TAYLOR








PERRY TWP  
T8N

SECTION 13  
RIW



PERRY TWP  
T8N

2633.40'

SECTION 14

RIW

2633.40

PLAT 54  
DISC MAKES  
NO EXPS FOR  
PLATS 81 & 82

2640.00'

PLATS 61 & 62  
HAVE NO  
DISC

PLAT 9  
MAKES NO  
EXP FOR  
PLAT 47

2640.00'

PLAT 14  
DISC MAKES  
NO EXPS FOR  
PLATS 36, 46, 49

PLAT 67  
DISC OVERLAPS  
PLAT 42


2640.00'

PLATS 17 THRU 21  
NO DIVISIONS  
IN DISC

2640.00'


2633.40'

D Taylor







SECTION 16  
RIW




COUNTRY CLUB TERRACE  
UNRECORDED PLAT  
T8N RIW  
SECTION 17












PERRY TWP SE 1/4 SECTION 20  
TOWNSHIP 8 NORTH RANGE 1 WEST



STONE 34.6 Rods S. of  
1320.0' NE cor. SE 1/4


1" = 200'

Note!!  
EVERY THING IN  
THIS SECTION (1/4)  
NEEDS RESURVEYED  
AND REDRAWN.  
THIS SHEET NOT  
ACCURATE EXCEPT  
1320.0' FOR GENERAL  
LOCATION OF PLATS.  
D. Combs  
Sept 29, 1977

PLAT #55 3.56 + .75 ac COULD NOT LOCATE TOTAL ACREAGE

PERRY  
TOWNSHIP 8 NORTH


SECTION 20  
RANGE 1 WEST




[illegible]


NOTE: SW 1/4 PLAT #27  
COULD NOT DETERMINE  
IF SOUTH PART EXIST.


NOTE NW 1/4 PLAT 145  
WAS UNABLE TO LOCATE  
OR DEFINE REMAINING  
PROPERTY 2.63ac  
ON BOOK.
















NOTE: ALL PROPERTIES  
IN THE E 1/2 OF THE SW 1/4 AND  
THE W 1/2 OF THE SE 1/4  
NEED TO BE REDRAWN  
AND RESURVEYED  
EXCEPT PLATS #9, 16, 17, 42, 48  
50, 52, 55, 59, 60, AND 92

COULD NOT LOCATE  
E OF HANDY ROAD  
BY DEEDS  
D. Combs  
10 August 1977

PLAT #43 WAS SHOWN  
ON OLD PLAT SHEET  
AT INTERSECTION OF  
HANDY + AIRLINE ROAD  
.33 acre. COULD FIND  
NO RECORD OF EXISTANCE






△ No Record, No Apparent Owner ★ Needs New Description 0 Needs New Survey


DRAWN: 7-7-77

PERRY SECTION 28  
TOWNSHIP 8 NORTH RANGE 1 WEST



⊙ Needs New Survey ★ Needs New Description NOTE: Unable to locate Plats #17 & 30 from description DRAWN: 7-1-77






Δ No Record, No Apparent Owner ⊙ Needs New Survey ★ Needs New Description NOTE: Unable to locate Plat #15 from description.  
DRAWN: 6 - 3 - 77


SECTION 33  
RANGE 1 WEST





PERRY  
TOWNSHIP 8. NORTH

SECTION 35  
RANGE 1 WEST



PERRY  
TOWNSHIP 8 NORTH

SECTION 36  
RANGE 1 WEST

